30 METAL MODEL



3DJS066



Insertion holes Fold

be seen as shown and then folded

Insertion lines can tabs are inserted




To create the best connections

Insert tab and bend 90 degrees for most visible areas

Insert tab and twist 90 degrees is best in some areas to ensure a tight connection



Metal sheet



In order to avoid possible injury from sharp edges, please carefully discard the metal sheet after parts have been removed

Assembly Flow Chart

