


3D METAL MODEL



3D-S008

To create the best connections

- Insert tab and bend 90 degrees for most visible areas
- ▲ Insert tab and twist 90 degrees is best in some areas to ensure a tight connection

Needle nose pliers are helpful for assembly


Legends:

- E Engraved side
- NE Non-engraved side
- Attention point

Insertion holes, Insertion tabs are inserted and then folded, Fold lines can be seen as shown here

Pull and Screw metal tab 90° to tighten

Metal sheets



⚠ In order to avoid possible injury from sharp edges, please carefully discard the metal sheet after parts have been removed

Assembly Flow Chart

1

2

3

4

5

6

