






360°  
view




To create the best connections

Insert tab and bend 90 degrees for most visible areas

Insert tab and twist 90 degrees is best in some areas to ensure a tight connection

Legends:

- Engraved side
- Non-engraved side
- Attention point




Insertion tabs are inserted and then folded

Fold lines can be seen as shown here

Insertion holes

Metal sheets



In order to avoid possible injury from sharp edges, please carefully discard the metal sheet after parts have been removed

Assembly Flow Chart

