

To create the best connections



Insertion tabs are inserted and then folded
Fold lines can be seen as shown here
Insertion holes



Needle nose pliers are helpful for assembly


● Insert tab and bend 90 degrees for most visible areas

▲ Insert tab and twist 90 degrees is best in some areas to ensure a tight connection



Pull and screw metal tab 90° to tighten

Metal sheets



⚠ In order to avoid possible injury from sharp edges, please carefully discard the metal sheet after parts have been removed

Assembly Flow Chart

