


Insertion tabs are inserted and then folded

Insertion holes

Fold lines can be seen as shown here




Needle nose pliers are helpful for assembly

**Metal sheet**

**To create the best connections**

- Insert tab and bend 90 degrees for most visible areas
- ▲ Insert tab and twist 90 degrees is best in some areas to ensure a tight connection



⚠ In order to avoid possible injury from sharp edges, please carefully discard the metal sheet after parts have been removed

**Assembly Flow Chart**

