



3D METAL MODEL

ASSEMBLING PROCEDURE



Assembling method

● Insert button hole, flat 90



▲ Insert button hole, rotate 90 degrees

